Item ID: D2917-2

Revision ID: В

Saddle RH **Item Name:**

Start Date:

09/30/2009

Start Qty: 10.00



Accept

Setup Start



Page 1

Stop

Required Date: 10/05/2009

Req'd Qty: 10.00

QC: Date:

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan: WW Date: 09-09-16 Tooling:

SPC (Y/N):

Date:

Date:

Run

Start



Stop

Sequence ID/ Work Center ID Operation

Description

Set Up/ **Run Hours** Draw Number Draw Rev.

Plan Accept Code **Qty**

Reject Qty

Reject

Insp. Number Stamp

Draw Nbr

Revision Nbr

D2917

100

Rev B

HAAS 1

HAAS CNC VERTICAL MACHINING #1

Memo

0.00

HAAS CNC vertical machine #1

• Program batch number Machine Step No 1 as per Folio FA439 and visually 1 inspect as per Dwg D2917 & attached Dimension Sheet Machine Step No 2 as per Folio FA439 and visually inspect as per Dwg D2917 & attached Dimension Sheet@Machine Step No.3 as per Folio

110

Mill Conv

Conventional Milling Machine

CONVENTIONAL MILLING MACHINE

QC2- Inspect parts off machine FAI/FAIB

10

Machine Keyway and inspect per Dwg D2917 & attached dimension sheet

and odloa/28

120

Memo

0.00

Ouality Control

Dart Ae W/O:				WORK ORDER (CHANGES			······································		
DATE	STEP		PR	OCEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						į				
Part No):		PAR #:	Fault Category:	NCR:	: Yes	No DQ	A:	Date:	
	R	Resolution:		Disposition:	QA: I	N/C C	losed:		Date: _	

NCR:	NCR: WORK ORDER NON-CONFORMANCE (NCR)							
	_	Description of NC		Corrective Action Section B			Anneoval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	QC Inspector
								:

						:		
	}							

В

Page 2

September 16, 2009 2:27:37 PM

Item ID:

D2917-2

Accept

Setup Start



Revision ID:

Start Date:

Item Name: Saddle RH

Required Date: 10/05/2009

09/30/2009

Start Qty: 10.00 Req'd Qty: 10.00

Cust Item ID:

Customer:

Draw

Number

Reference:

Approvals:

Date:

Tooling:

Date:

Run

Reject

Qty

Start

Stop

SPC (Y/N):

Date:

Draw

Rev.

Plan

Code

Stop

Insp.

Stamp

Sequence ID/ Work Center ID

130

Quality Control

Operation Description

QC8- Inspect parts - second check

Memo

QC: _____ Date: ____

0.00

Set Up/

Run Hours

Qty

Accept

Reject

Number

140

HandFinish

Hand Finishing

Chemical Conversion Coat per QSI005 4.1

1 09/09/30



Memo

0.00

150




Powder Coating

White Gloss(Ref:4.3.5.1) per QSI005 4.3-Alum

M 112260

0.00



II 04/04/30





Memo

1 1000 MIOVEN TEMPERATURE: START TIME:

1.30 par FINISH TIME:

320%

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
		No. A						, roa mg,					
								:					
Part No	•	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQ	A:	Date: _					
		esolution:											
NCR:			WORK ORD	ER NON-CONFORM	ANCE (NCF	R)							
DATE	STEP	Description of NC			ion B	Verific	cation	Approval	Approval				
DAIL	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti	on C	Chief Eng	QC Inspector				
	i.												
									į				
		About of resident to the second secon											

Work Order ID 52128

Page 3

September 16, 2009 2:27:37 PM

Item ID:

D2917-2

Accept

Setup Start

Stop

Revision ID: Item Name:

Start Date:

В

Required Date: 10/05/2009

Saddle RH

09/30/2009

Start Qty: 10.00

Req'd Qty: 10.00

Cust Item ID:

Customer:

Reference:

Approvals:

Date:

Tooling:

Date: _____

Rev.

Date:

Run Start

Stop

Process Plan:

Date:

SPC (Y/N):

Set Up/

Draw

Number

Draw

Plan Code Accept

Reject

Number Stamp

Insp.

Sequence ID/ **Work Center ID**

160

Quality Control

Operation Description

QC3-Inspect Part Finish

Memo

Run Hours

Oty

Qty

Reject

170

Packaging Packaging

0.00

Memo

Identify as per dwg & Stock Location:

0.00

180

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

09/10/01 HJ MF 09-10-01

Dart Aerospace Ltd

W/O:		WORK ORDER CH	HANGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #: Fault Category:	NCR : Yes	No DQ	A:	Date:	

Part No:	PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
Re	solution:	Disposition:	QA: N/C Closed:	Date:

NCR:	!	WORK ORDER NON-CONFORMANCE (NCR)									
	T	Description of NC		Corrective Action Section B			Approval	Approval			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Chief Eng	QC Inspector			
		•									
		, T									
······································											
				·							
							1				

Picklist Print

September 16, 2009 2:27:37 PM

Work Order ID: 52128

Parent Item:

D2917-2RevB

Parent Item Name:

Saddle RH



Start Date: 09/30/2009

Required Date: 10/05/2009

Start Qty: 10.00

Required Qty: 10.00

Component Item ID/ Item Name

Comments:

Replacement Mfg/ Item ID

Purch

Primary Item Location Last Location

Route Seq ID Unit of Measure Hand

Qty on

Qty Remaining Qty To Pick Issued Date Issued

Status

D6102-010RevD

Manufactured

No

100

Each

6.0000

Loc Code

10.0000

Saddle Billet

Warehouse Location

Main Warehouse MAT

6

51423

Loc Oty

B52067

10 onl 69/09/27

Page 1

Dart Aerospace	Ltd
-----------------------	-----

W/O:		WORK ORDER CHA	WORK ORDER CHANGES							
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
							!			
Dort No	1						1			

Part No:	PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
Resoluti	on:	Disposition:	QA: N/C Closed:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)										
		Description of NC		Corrective Action Section B			Approval	Approval				
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Chief Eng	QC Inspector				
•												
						754.7						
,												

DART AEROSPACE LTD	Work Order:	52128
Description: Saddle RH	Part Number:	D2917-2
Inspection Dwg: D2917 Rev. A1		Page 1 of 1

Inspect dimensions highlighted on inspection sheet drawing D2917 Rev. A1 and record below:

•				1		ual Dimensi	01.0		
Dim	Min	Max	Go/No Go Gauge	1	2	3	4	Ву	Date
Α	0.175	0.205		.190	.190	.190	.189		
В	0.090	0.110		.095	-099	-103	.096	·	
С	0.250	0.270		.258	259	.258	258		
D	1.599	1.619		1.1009	1.608	1.607	1.608		
E	0.180	0.220		.180	180	.180	.180		
F	0.277	0.297		281	282	.282	. 284		
G	1.385	1.400		1.389	1.390	1.390	1.388		
Н	3.170	3.230		3.190	3.199	3.100	3.200		
1	0.175	0.217		.175	.175	176	.179		,
J	0.470	0.530		.500	.500	. 506	.500		
K	1.498	1.508		1.502	1.500	1.504	1.500		
L	4.436	4.446		4.438	4.440	4.441	4.443		
М	0.257	0.262	DT8683	,259	.259	.259	,259		
N	1.225	1.235		1.227	1.228	1,228	1.228		
0	1.103	1.113		1.108	1.108	1.108	1.10%		***
Р	0.470	0.530		.500	1.108	500	.500		
Q	0.438	0.443	DT8682	.440	.440	.440	.440		
R	0.490	0.510		500	502	500	.503		
S	1.745	1.755		1.750	1.750	1.750	1.750		
T	7.990	8.010		8.000	2.000	8.000	8.000		
U	3.495	3.505		3.500	3.500	3,500	3.500		
V	0.175	0.205		.203	-205	-205	.205		
W	1.990	2.010		2.002	2.005	2.005	2.002		
Х	0.760	0.765	10	.740	.760	.761		"	
Y	0.307	0.312		310	.3/0	.3//	761		
Z	0.615	0.635	<u> </u>	1628	. 635	.628	627		
AA	0.177	0.197		.184	-186	186	.186		
AB									
AC									
AD							· ·		 -,
AE									-
AF									
AG									
AH									

	1
Measured by:	Audited by
Date: 09/09/28	Date: 09.09.29

Rev	Date	Change	Revised by	Approved
Α	04.08.12	New Issue	KJ/JLM , ,	-1
В	04.09.20	Added DT8683 & DT8682	KJ/JLM	Sul
			· ()	

Dart Aerospace	Ltd
----------------	-----

W/O:	-		W	ORK ORDER CHANG	FS				
DATE	STEP	PRO	CEDURE CHA	•	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									:
Part No	•	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQ	A:	Date:	
	R	esolution:	Dispositio	n:	QA: N/C (Closed:		Date: _	
NCR:		V	VORK ORD	ER NON-CONFORM	ANCE (NC	R)	- .		
DATE	STEP	Description of NC	Initial		tion B		cation	Approval	Approval
		Section A	Chief Eng	Action Description Chief Eng	Date		on C	. Chief Eng	QC Inspector
				,					
		•							
		:							

DART AEROSPACE LTD	Work Order:	50125
Description: Saddle RH	Part Number:	D2917-2
Inspection Dwg: D2917 Rev. A1		Page 1 of 1

Inspect dimensions highlighted on inspection sheet drawing D2917 Rev. A1 and record below:

				Re	corded Act	ual Dimensi	ons		
Dim	Min	Max	Go/No Go Gauge	18	16	87	18	Ву	Date
Α	0.175	0.205		187	138	.188	./88		
В	0.090	0.110		.090	.090	.090	.090		
С	0.250	0.270		1.257	257	.258	.258		
D	1.599	1.619		1.607	1.408	1.608	1.609		
Ε	0.180	0.220		.180	-180	,180	180		
F	0.277	0.297		1.283	282	1.370	283		
G	1.385	1.400		1.387	1.388	1.370	1.389		
Н	3.170	3.230		3.200	3.200	3.200	3.200		
ı	0.175	0.217		1.177	1.177	.177	176		
J	0.470	0.530		· S00	500	.500	500		
K	1.498	1.508		1.503	1.502	1.501	1.501		
L	4.436	4.446		4.442	4.444	4.441	4.442		
M	0.257	0.262	DT8683	.259	.259	.259	-259		
. N	1.225	1.235		1.231	1.229	1.228	1,230		
0	1.103	1.113		1.1010	1.106	1.106	1.107		
Р	0.470	0.530		.500	.500	-500	.500		
Q	0.438	0.443	DT8682	440	440	,440	440		
R	0.490	0.510		.503	, 503	.504	-500		
S	1.745	1.755		1.750	1.750	1.750	1.750		
Т	7.990	8.010		8.000	3.DD/	8.001	8,000		
U	3.495	3.505		3.500	3.500	3.500	3.500		
V	0.175	0.205		205	205	.205	.205		
W	1.990	2.010		2.003	2.003	2.005	2.004		
X	0.760	0.765		761	7/01	760	,760		
Υ	0.307	0.312		.3//	.371	-760 -310	.310		
Z	0.615	0.635		.429	.1.27	.627	.625		
AA	0.177	0.197		-186	. 186	.184	.188		
AB									
AC									
AD									
AE									
AF					•				
AG									
AH									
	Acc	ept/Reje	ct						

Measured by:	Audited by
Date: 09/09/28	Date: 09.09.29

Rev	Date	Change	Revised by	Approved
Α	04.08.12	New Issue	KJ/JLM 1.0	
В	04.09.20	Added DT8683 & DT8682	KJ/JLM O	


DART AEROSPACE LTD	Work Order:	50128
Description: Saddle RH	Part Number:	D2917-2
Inspection Dwg: D2917 Rev. A1		Page 1 of 1

Inspect dimensions highlighted on inspection sheet drawing D2917 Rev. A1 and record below:

		,		Re	corded Actua	al Dimensi	ons		
Dim	Min	Max	Go/No Go Gauge	Xq	210	ß	¥	Ву	Date
Α	0.175	0.205		187	-137				
В	0.090	0.110		.090	.090				
С	0.250	0.270		.258	-253				
D	1.599	1.619		1.1.10	1.610				
E	0.180	0.220		1.610	.120				
F	0.277	0.297		.283	-130 -233				
G	1.385	1.400		1.389	1.389				
Н	3.170	3.230		3.200	3.200				,
i	0.175	0.217		-180	130				•
J	0.470	0.530		.5700	. 500				
K	1.498	1.508		1.501	1.501				
L	4.436	4.446		4.442	4.442				
M	0.257	0.262	DT8683	.259	259				
N	1.225	1.235		1.229	1.229				
0	1.103	1.113		1.106	1.106				
Э	0.470	0.530		,50	.500				
Ø	0.438	0.443	DT8682	.440	-440				
R	0.490	0.510		500	.500				
S	1.745	1.755		1.750	1.750				
T	7.990	8.010		2.000	8.00			· .	
U	3.495	3.505		3.500	3.50				
V	0.175	0.205		.205	,200				
W	1.990	2.010		2.003	2.000				
Χ	0.760	0.765		.760	760				
Υ	0.307	0.312		1310	,310				
Z	0.615	0.635		1625	-126,				
AA	0.177	0.197		137	137				
AB									
AC									
AD									
AE					·				
AF									
AG									
AH		ept/Reje							

		/_ /	- 2
Measured by:	ont, la	8/	Audited by
Date:	09/09/28/09	7/09/29	Date: 64. 09. 29

A 04.08.12 New Issue KJ/JLM	Approved	Revised by	Change	Date	Rev
	21	KJ/JLM 1.A	New Issue	04.08.12	Α
B 04.09.20 Added D18683 & D18682 KJ/JLIM 54		KJ/JLM	Added DT8683 & DT8682	04.09.20	В



Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES										
DATE	STEP	PROC	CEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
,												
							•					
Part No	•	PAR #:	Fault Category:			ICR: Yes No DQA: Date:						
	R	esolution:	Disposit	tion:	_ QA:	A: N/C Closed:			Date:			
NCR:		W	ORK OR	DER NON-CONFORMA	ANCE	(NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B		ion B	<u> </u>	Verification		Approval	Approval		
			Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti	on C	Chief Eng	QC Inspector		
			,									
				·								
								•				
							·	•				